

The Solution for Drying Project Scope & Pricing

Mark Fiutem



32828

Cost Evaluation w/o Drying Log information

Cost Evaluation Report

Claim Information

Insurance Company

Adjuster Claim Number Insured Address

CityOrlandoCause of LossOther - supply line rupture

Orlando State FL Zip

Comparison Overview

	Invoice Amount	Rec. Amount	Cost Differential
Total Line Items Amount	\$15,008.60	\$4,792.46	\$10,216.14
Tax	\$0.00	\$0.00	Not evaluated
Rebuild	\$0.00	\$0.00	Not evaluated
Totals	\$15,008.60	\$4,792.46	\$10,216.14

Cost per Category Breakdown for Water Mitigation

	Invoiced	Recommended	Differential
Negative Air Cost	\$1,319.88	\$0.00	\$1,319.88
Air Mover Cost	\$2,999.60	\$1,727.40	\$1,272.20
Antimicrobial Cost	\$130.00	\$130.00	\$0.00
Move and Reset Cost	\$169.30	\$168.76	\$0.54
Debris Removal Cost	\$127.77	\$127.77	\$0.00
Dehumidification Cost	\$3,263.76	\$897.39	\$2,366.37
HEPA Vacuum Cost	\$0.00	\$0.00	\$0.00
HVAC Cost	\$0.00	\$0.00	\$0.00
Other Cost	\$2,501.44	\$0.00	\$2,501.44
PPE Cost	\$0.00	\$0.00	\$0.00
Labor Cost	\$4,370.94	\$1,741.14	\$2,629.80
Supply Cost	\$125.91	\$0.00	\$125.91
Total	\$15,008.60	\$4,792.46	\$10,216.14

Summary

Water Damage Class Class 2

Water Source Category 1 - Clean

Square Footage1329Cubic Footage15392Linear Feet425Number of Enclosures10Water Damaged Floors1

Project Duration (days) Invoiced 4 Recommended 3



The Solution for Drying Project Scope & Pricing



Summary of Tasks

Category	Task	Quantity	Invoiced Unit Cost	Recommended Unit Cost	Cost Differential
Antimicrobial Cost	Apply anti-microbial agent	650	\$0.20	\$0.20	\$0.00
Move and Reset Cost	Block and pad furniture in room - after hours	2	\$55.22	\$54.95	\$0.54
	Content Manipulation charge - per hour	2	\$29.43	\$29.43	\$0.00
Debris Removal Cost	Haul debris - per pickup truck load - including dump fees	1	\$127.77	\$127.77	\$0.00
Other Cost	Overhead and Profit 2 EA @ 1250.72 for 2501.44	1	\$2,501.44	\$0.00	\$2,501.44
Labor Cost	Supplies and Materials 1 @ 35.00	1	\$35.00	\$0.00	\$35.00
	Administrative 1 @ 125.00	1	\$125.00	\$0.00	\$125.00
	Carpet Clinic Invoice 1150.00	1	\$1,150.00	\$0.00	\$1,150.00
	Moisture Inspection 1 @ 125.00	1	\$125.00	\$0.00	\$125.00
	Drill holes for wall cavity drying - After hrs	12	\$0.57	\$0.57	\$0.00
	Emergency service call - after business hours	1	\$199.80	\$198.80	\$1.00
	Equip. setup, take down & monitoring - after hrs	3	\$70.80	\$70.80	\$0.00
	Equipment decontamination charge - per piece of equipment	22	\$35.00	\$0.00	\$770.00
	Equipment setup, take down, and monitoring (hourly charge)	5	\$65.67	\$47.33	\$91.70
	Equipment setup, take down, and monitoring (hourly charge)	1	\$65.64	\$0.00	\$65.64
	Tear out baseboard	182.2	\$0.86	\$0.34	\$94.74
	Tear out non-salv solid/eng. wood flr & bag for disposal	299.22	\$2.43	\$2.42	\$2.99
	Tear out wet drywall, cleanup, bag for disposal	190	\$0.73	\$0.73	\$0.00
	Water extraction from hard surface floor	703	\$0.47	\$0.23	\$168.72
Supply Cost	Add for HEPA filter (for negative air exhaust fan)	9	\$13.99	\$0.00	\$125.91

Summary of Equipment Rental

Category	Task	Invoiced Quantity	Invoiced Unit Cost	Recommended Quantity	Recommended Unit Cost	Cost Differential
Negative air cost	Negative air	12	\$109.99	0	\$0.00	\$1,319.88
Air Mover Cost	Air mover (per 24 hour period) - No monitoring	40	\$32.99	30	\$25.58	\$552.20
	Wall cavity drying-Dctd type (per 24 hr period) No monit.	12	\$140.00	12	\$80.00	\$720.00
Dehumidification cost	Dehumidifiers	24	\$135.99	9	\$99.71	\$2,366.37

Approximate Cost Differential Distribution for Negative air/scrubbers

Reduced Project Duration	\$263.98
Reduced Unit Cost and/or Negative air/scrubbers Capacity	\$1,055.90
Total	\$1,319.88

Approximate Cost Differential Distribution for Selected Air Movers (centrifugal and axial fans)

Reduced Project Duration	\$290.87
Reduced Unit Cost and/or Air Movers Capacity	\$261.33
Total	\$552.20

Approximate Cost Differential Distribution for Dehumidification



The Solution for Drying Project Scope & Pricing



\$504.38

\$1,861.99

\$2,366.37

Reduced Project Duration
Reduced Unit Cost and/or Dehumidification Capacity
Total

Project Comments

rw_24982

Note: Any user of the information contained in this Report uses it at their own risk. There is no guarantee that the information contained herein is free from error. The information is calculated based on supplied data. To the extent that the such data is inaccurate, or there are changes in the environmental conditions that are not included in the input data, e.g. changes in air temperature or relative humidity levels, the report will be inaccurate.